



COME TO RELAX • STAY TO EXPLORE

## Road Department

### **Commodore Ln.**

To meet the County Road Resolution, we have listed some suggestions:

12" x 45' driveway culvert at 34 Commodore (Floyd)

12" x 26' driveway culvert at 186 Commodore (Glenn)

12" x 26' driveway culvert at 290 Commodore (Mitchell)

12" x 26' cross culvert between Jameson & Glenn Residences and base asphalt installed

Ditches will have to be installed on the roadway for it to drain properly

The road was drilled in 3 locations. The base asphalt measured 2.5" in two locations, but before the cul-de-sac, it only measured 1.75". This area would require more base asphalt to meet specs. The road is breaking up in several other locations and that would also need to be repaired.